

# RESISTANCE TO CHEMICALS

## Key

- A0 No change in lightness or colour
- A1 Somewhat lighter surface
- A2 Lighter surface
- A3 Somewhat darker surface
- A4 Darker surface
- A5 Somewhat discoloured surface
- A6 Discoloured surface
  
- B0 No change in gloss or matness
- B1 Somewhat mat surface
- B2 Mat surface
- B3 Somewhat glossy surface
- B4 Glossy surface
  
- C0 No change in patchiness
- C1 Somewhat patchy or spotty surface
- C2 Patchy or spotty surface
  
- D0 No change in evenness
- D1 Somewhat uneven or porous surface
- D2 Uneven and porous surface
- D3 Somewhat crackled surface
- D4 Crackled surface
  
- E0 No brittleness, stickiness or softening
- E1 Some surface brittleness
- E2 Brittle surface
- E3 Some surface stickiness
- E4 Sticky surface
- E5 Somewhat softened
- E6 Softened
  
- F0 No change in size or flatness
- F1 Some swelling
- F2 Swelling
- F3 Slight shrinkage
- F4 Shrinkage
- F5 Some bulging
- F6 Bulging or distortion
  
- G0 No delamination
- G1 Delamination of two or more layers
  
- H Other changes noted (text en clair)