

## Additional maintenance recommendation for iQ floorings.

**In areas with very frequent high traffic and high amount of grit on the floor, a more frequent cleaning and dry buffing treatment will be required. If this frequency has not been put in place, the result will be a floor with a dull and/or scratched surface.**

**In such case a more thorough treatment will be needed to be able to repair and get the surface back to a normal condition. After this repair treatment is done shall our normal recommendations be followed.**

**Below two methods are described. One, "Light", for less worn areas and "Heavy" for more scratched surfaces.**

**Please follow these steps carefully:**

### « LIGHT »

- Machine scrub with blue 3M pad and detergent. Use a Maintainer\*, for example Diversey Tensol, and a heavy machine, preferably a Duo Speed. Use low speed 165 to 185 rpm. Scrub cross-wise.
- Wet vacuum slurry carefully.
- Rinse with pure water. Wet vacuum once again.
- Dry buff with approx. 330 rpm (the highest on the Duo Speed machine) and red 3M pad.
- If high gloss is requested, dry buff on high speed with red 3M pad.
- 

### « HEAVY »

- Machine scrub with brown 3M pad and detergent. Use a Maintainer\*, for example Diversey Tensol, and a heavy machine, preferably a Duo Speed. Use low speed 165 to 185 rpm. Scrub cross-wise.
- Wet vacuum slurry carefully.
- Rinse with pure water. Wet vacuum once again.
- Dry buff with approx. 330 rpm (the highest on the Duo Speed machine) and blue 3M pad.
- Dry buff once again as above but this time use red pad.
- If high gloss is requested, dry buff on high speed with red 3M pad.

## GENERAL ADVICE

- It is highly recommended to use machine cleaning, so called Auto Scrubber Driers, whenever possible. Today there are efficient machines developed also for use in smaller areas.
- Adapt the cleaning frequency to the soiling level. Cleaning more often reduces unnecessary wear and need of maintenance.

---

\* Follow manufacturers dosing instructions carefully.

*If any doubts or clarifications should be needed, please contact your local Tarkett representative for further information.*